

Express Stairs Yorkshire

Job & Site Details Cover Sheet

b:		PO:		
JOB DETAILS		Job Number:	9358	
Customer Details			Site Details	
Company Name:		Site Company Name:		
Contact Name: Amy Herron		Site Contact Name:	Amy Herron	
Address: 9 the willows,		Address:	9 the willows,	
Dalton, Thirsk		Address.	Dalton, Thirsk	
Postcode: YO7 3NJ		Destando		
		Postcode:	Yo73nj	
Phone No: 07850927445		Phone No:		
Mobile:		Mobile:		
Job:				
1 No Single Staircase				
No Assembled				
No Assembled				
No Assembled				
No Assembled Single Staircase x 1 Building Regulations:	UK 1			
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One:	1			
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction:	1 Right			
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One:	1 Right 1			
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two:	1 Right 1 11			
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise:	1 Right 1			
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers:	1 Right 1 11 2750mm	construction		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type:	1 Right 1 11 2750mm 14 Closed tread			
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers:	1 Right 1 11 2750mm 14 Closed tread	ood Pine (Furniture Grade)		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type: String Material:	1 Right 1 11 2750mm 14 Closed tread 32mm Redw 22mm MDF	ood Pine (Furniture Grade) Treads		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type: String Material: Tread Material:	1 Right 1 11 2750mm 14 Closed tread 32mm Redwi	ood Pine (Furniture Grade) Treads isers		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type: String Material: Tread Material: Riser Material: Winder Tread Material:	1 Right 1 2750mm 14 Closed tread 32mm Redw 22mm MDF 9mm MDF R	ood Pine (Furniture Grade) Treads isers		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type: String Material: Tread Material: Riser Material: Riser Material: Winder Tread Material: Individual Rise:	1 Right 1 2750mm 14 Closed tread 32mm Redw 22mm MDF 9mm MDF R 22mm MDF R	ood Pine (Furniture Grade) Treads isers		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type: String Material: Tread Material: Riser Material: Riser Material: Winder Tread Material: Individual Rise: Going:	1 Right 1 2750mm 14 Closed tread 32mm Redw 22mm MDF 9mm MDF R 22mm MDF 7 196.43mm	ood Pine (Furniture Grade) Treads isers		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type: String Material: Tread Material: Riser Material: Riser Material: Winder Tread Material: Individual Rise:	1 Right 1 2750mm 14 Closed tread 32mm Redw 22mm MDF 9mm MDF R 22mm MDF 196.43mm 220mm	ood Pine (Furniture Grade) Treads isers		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type: String Material: Tread Material: Riser Material: Riser Material: Minder Tread Material: Individual Rise: Going: Overall String Width:	1 Right 1 11 2750mm 14 Closed tread 32mm Redw 22mm MDF 9mm MDF R 22mm MDF 196.43mm 220mm 900mm	ood Pine (Furniture Grade) Treads isers Treads		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type: String Material: Tread Material: Riser Material: Riser Material: Minder Tread Material: Individual Rise: Going: Overall String Width: Nosing Style:	1 Right 1 11 2750mm 14 Closed tread 32mm Redw 22mm MDF 9mm MDF R 22mm MDF 196.43mm 220mm 900mm Half Round	ood Pine (Furniture Grade) Treads isers Treads t		
No Assembled Single Staircase x 1 Building Regulations: Number of Treads in Flight One: Turn One Direction: Number of Treads in Turn One: Number of Treads in Flight Two: Rise: Number of Risers: Tread Type: String Material: Tread Material: Riser Material: Riser Material: Minder Tread Material: Individual Rise: Going: Overall String Width: Nosing Style: Feature Tread:	1 Right 1 11 2750mm 14 Closed tread 32mm Redw 22mm MDF 9mm MDF R 22mm MDF 196.43mm 220mm 900mm Half Round bullnose righ	ood Pine (Furniture Grade) Treads isers Treads t		

Job No	
Region	

Company Registration Number: 11377593 | VAT Registration Number: 356857550